



0444

Technical Report 24795-SRL-RP-XT-001-PI

Project

The Laboratory Measurement of the Sound Reduction Index a Window

Prepared for

Hansen Facades

By

Kieron Farrow

Published

17 May 2021





Page 2 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

Quality Assurance						
Project Title	The Laboratory Measurement of the Sound Reduction Index a Window					
Document Title	Laboratory Test Report					
Client	Hansen Facades					
Client Address	Unit 2.08 Hollinwood Business Centre Oldham OL8 3QL					
Author	Kieron Farrow					
Checker	Allen Smalls					
Report Number	24795-SRL-RP-XT-001-P1					

Report Version History

Version	Date	Comments
PI	17/05/2021	

Kieron Farrow

Kieron Farrow Tester For and on behalf of SRL Technical Services Limited Tel: 01787 247595 Email: kfarrow@srltsl.com

Allen Smalls Quality Manager



Test Report No: 24795-SRL-RP-XT-001-PI

Page 3 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

Contents

1.0	Description of Test	4
2.0	Results	5
Data S	heets I to 3	6
Drawir	ng I – Frame Details	9
Photog	raph I – Test SampleI	0
Appen	dix A - Details of Measurements I	I
Appen	dix B – Test ProcedureI	3
Appen	dix C – Measurement UncertaintyI	5





Page 4 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

1.0 Description of Test

Tests have been done in SRL's Laboratory at Holbrook House, Sudbury, Suffolk, to determine the sound reduction index of a window in accordance with BS EN ISO 10140-2:2010.

The results are given in 1/3rd octave bands over the frequency range 50 Hz to 10 kHz, which is beyond that required by the test standard. Measurements outside the standard frequency range are not UKAS accredited.

1.1 Description of Sample

Various glazing specifications were tested in a window frame. See Data Sheets 1 to 3, Drawing 1 and Photograph 1 for details.

Sampling plan:	Enough for test only
Sample condition:	New
Details supplied by:	Hansen Facades
Sample installed by:	Hansen Facades

1.2 Sample Delivery Date

27 April 2021

1.3 Test Procedures

The sample was mounted/located and tested in accordance with the relevant standard. The details of measurements are given in Appendix A. The method and procedure are described in Appendix B. The measurement uncertainty is given in Appendix C.





Page 5 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

2.0 Results

The results of the measurements and subsequent analysis are given in Data Sheets I to 3 and summarised below.

Results relate only to the items as received and tested.

SRL Test No.	Description in Brief	R _w (C; C _{tr})
I	39.5mm thick DG unit, 8mm heat strengthened outer, 18mm argon filled spacer, 13.5mm PVB laminated inner	37 (0; -2) dB
4	39.5mm thick DG unit, 8mm heat strengthened outer, 18mm argon filled spacer, 13.5mm acoustic interlayer laminated inner	40 (0; -3) dB
5	40.3mm thick DG unit, 8.8mm PVB laminate outer, 18mm argon filled spacer, 13.5mm acoustic interlayer laminated inner	44 (-2; -5) dB



Test Report No: 24795-SRL-RP-XT-001-PI

Page 6 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

		ee SRL Repo																
	Laboratory M	easurement	of Soun	d Re	duction	Inde					40-2:	2010						
Test Number:		I							Roo				Sour				eivin	-
Client:	Hans	en Facades							-	erati			12.3				.5 °C	,
Test Date:	1	27/04/2021					4	Air H	lum	idity:			51	%		5	2 %	
Sample Height:		2.05	m				N	/olu	me:				54.6	m³		52	.8 m³	
Sample Width:		2.37	m				4	Air P	ress	ure:				10	002 m	ıbar		
Sample Weight:		47.9	kg/m²															
Product Identification:	39.5mm thick DG unit inner	, 8mm hea	t stren	gthe	ned ou	iter,	18r	nm :	argo	n fille	ed sp	acer	, 13.	5mn	ז PVE	3 Iami	inate	d
			7	70.0 ·														
Fraguanay Hz	Sound Reduction Ind	ex, dB				r						Ц.						I
Frequency Hz							—			Redu	ction							
	⅓ Oct	Octave						I	ndex									
50+	34.0		4	50.0				- F	Rw re	ferenc	e curv	eL						
63+	27.6	28.9	C	.0.0														-
80+	27.6					[1
100	24.6																	
125	22.9	25.1																/
160	31.6		5	50.0								_					\square	-
200	33.4																\boldsymbol{V}	l
250	33.9	34.0															1	l
315	34.7																	l
400	33.8		dB												_	Ι.		l
500	32.5	33.5	×a 4	10.0							_	<u> </u> .				4		_
630	34.3		l								- † -				\land			l
800	36.9		tion									1						I
1000	36.8	36.6	Sound Reduction Index, dB 0.07 3000				\vdash	Γ.	\sim	\checkmark	1							l
1250	36.2		I Re			K		1		[l
1600	36.6		oun	80.0			1					1				-		1
2000	38.8	38.6	S		/		1											I
2500	42.0	7			L //	1												
3150	47.0				\/.⁄	1												
4000	51.9	50.1	2	20.0												\square		-
5000	55.1	7	2		1													
6300+	55.8																	
8000+	57.5	55.9																
10000+	54.9																	1
Average 100-3150	34.8	SRL Version 20.11.24.15.0 9	I	0.0							+							
	ent corrected for backgrou																	I
	ent limited by background	-																
	v beyond standard and not	UKAS accr	edited	0.0												\perp		
Rating according to	BS EN ISO 717-1:2013				125	091	200	250.	- C 15	200	ò	0	80 J y, Hz	0071	2000 -	2500 -	3150 -	S

Template Ref: Lab Edition 5 – Mar 2021

Return to Contents



Test Report No: 24795-SRL-RP-XT-001-PI

Page 7 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

	Se	e SRL Repo	ort 247		<u>a She</u> RL-RP-			-PI	for fu	ıll de	tails									
	Laboratory Me											140-	2:20	10						
Test Number:	· · ·	4								Roo					ourc	е		Rec	eivin	g
Client:	Hanse	en Facades						A	ir T	emp	oerat	ture	:	12	2.8 °C	2		13	3°C	
Test Date:	2	7/04/2021						A	lir ⊦	lum	idity	:		5	64 %			5	5 %	
Sample Height:		2.05	m					V	'olu	me:				54	ł.6 m	3		52	.8 m³	
Sample Width:		2.37	m					A	ir P	ress	ure:					100	0 mb	ar		
Sample Weight:		N/A	kg/m ²																	
	39.5mm thick DG unit,	8mm hea	at stre	ngth	ened	out	er,	l8m	ım a	rgoi	n fille	ed s	pace	er, I	3.5m	m a	cous	tic		
Product Identification:	interlayer laminated in	ner																		
				70.0	1													Τ		
	Sound Reduction Inde	ex, dB					_	-												
Frequency Hz					:				<u> </u>	ound	l Redu	uctior	ı							
	⅓ Oct	Octave	1		1				I	ndex										
50+	35.4			60.0					— F	lw re	feren	се си	IVP							
63+	28.7	30.8		00.0				_			en									
80+	30.6						L													
100	25.5				:															/
125	23.9	26.0			:															/
160	31.4			50.0	-							_	_		_	_	_		\square	
200	35.1]													/	1	
250	37.8	36.5]															
315	37.1		-l		:										-		- -/	4		
400	35.8		.08 Sound Reduction Index, dB .08		:								- †	-			1			
500	38.0	36.8		40.0								-	\checkmark	\checkmark	\top	1	-	-		
630	37.0							/	\sim	Ń	\land	\checkmark								
800	40.6		ction		1		/		/	```										
1000	39.3	40.0	equi	1			/		1											
1250	40.2		A P	30.0		_/		/												
1600	40.3		uno	50.0	:		ŗ													
2000	41.6	41.9	S			//	•													
2500	44.8	ļ				"														
3150	48.9	- <u>-</u>			11															
4000	52.3	51.6		20.0	+							+			_	+	+	+-		
5000	56.6																			
6300+	55.7																			
8000+	57.5	55.5			1															
10000+	54.0	SRLVersion		10.0	1															
Average 100-3150	37.3	20.11.24.15.0 9		10.0]															
* shows measurem	ent corrected for backgrou	nd	-																	
> shows measurem	ent limited by background				1															
	beyond standard and not	UKAS accr	edited																	
	BS EN ISO 717-1:2013			0.0	8 <u>2</u>		2 9	2 9	2 5				 ≥				+	+ 8 '		2
R _w (C;C _{tr})=	40 (0;-3) dB				2 2	071			7		500	1 63	8	80 ncy,	г 125	1600	2000	250	3150	



Test Report No: 24795-SRL-RP-XT-001-PI

Page 8 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

	52	e SRL Repo	ort 247		a She		01-1	PIfo	r full	detai	ls									
	Laboratory Me)-2:2	010							
Test Number:		5							st Ro					Soui	ce		F	Recei	vin	g
Client:	Hans	en Facades							r Ter			e:		12.4				12.5		-
Test Date:		8/04/2021							Hu	•				51	%			51	%	
Sample Height:		2.05	m						lume					54.6	m³			52.8	m³	
Sample Width:		2.37	m					Aiı	r Pre	ssur	e:				ç	997 r	nbar			
Sample Weight:		N/A	kg/m²																	
Product Identification:	40.3mm thick DG unit, laminated inner	. 8.8mm P	VB lan	nina	te out	er,	8m	im ai	rgon	fille	d spa	acer	, 13.	.5mi	n ao	cous	tic i	nter	laye	er
]	70.0	1															
F	Sound Reduction Ind	ex, dB					L						_							
Frequency Hz					1		-				educti	on								
	⅓ Oct	Octave]]				Inde	ex										
50+	35.7]	60.0	1				• Rw	refer	ence o	urve								
63+	27.3	30.2		00.0					1.144											
80+	31.4						Ļ													/
100	25.5																			/
125	24.9	26.7																		
160	35.3			50.0	1				_	_	_							\mathcal{A}		
200	36.6				1													Z_		
250	39.2	38.3	38.3		1															
315	39.8]						· '									
400	37.7		dB						/	1										
500	41.2	39.7	Sound Reduction Index, dB	40.0					术		4									
630	41.1		- Inc		1			//		Y										
800	42.9		tior			r	1													
1000	42.5	43.I	onpa	/		1														
1250	44.0		d Re	30.0 ·	-	1.1														
1600	45.4		unc]	ľΤ														
2000	46.7	46.6	Ň		//															
2500	48.0		l		\square															
3150	50.9				1															
4000	53.9	53.4		20.0	↓				_	_	_									
5000	58.2																			
6300+	57.8]															
8000+	59.1	56.8]															
10000+	54.8																			
Average 100-3150	40.1	SRL Version 20.11.24.15.0 9		10.0		+		+	+	+	+							+	+	
	I ont corrected for backgroup	-	1		1															
	ent corrected for backgrou nent limited by background	nu																		
	/ beyond standard and not	UKAS accr	redited																	
	BS EN ISO 717-1:2013	UNAS ALLI		0.0				\rightarrow												
isaulig according to	44 (-2;-5) dB				125	160	200	250	315	400	500	g requ						3150	4000	200




Test Report No: 24795-SRL-RP-XT-001-PI

Page 9 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

Drawing 1 – Frame Details







Page 10 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

Photograph 1 – Test Sample





Test Report No: 24795-SRL-RP-XT-001-PI

Page || of |6

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

Appendix A - Details of Measurements

A1.	Location
	Sound Research Laboratories
	Holbrook House
	Little Waldingfield
	Sudbury
	Suffolk
	CO10 0TF

A2. Test Dates

27 & 28 April 2021

A3. Tester

Kieron Farrow of SRL Technical Services Limited

A4. Instrumentation and Apparatus Used

Make	Description	Туре
Abtronix	Microphone Multiplexer	
EDI	Microphone Power Supply Unit	
Norwegian Electronics	Multichannel Sound Level Meter	Nor850
	Rotating Microphone Boom	265
Template Ref: Lab Edition 5 – Mar 2021	Return to Contents	



Test Report No: 24795-SRL-RP-XT-001-PI

Page 12 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

Brüel & Kjaer	Windshields	UA0237
	Pre Amplifiers	2669C
	Microphone Calibrator	4231
	Omnipower Sound Source	4296
Larson Davis	12mm Condenser Microphone	2560, 377A60
Oregon Scientific	Temperature & Humidity & Probe	THGR810
ТОА	Graphic Equalizer	E-1231
Crown	Class D Amplifier	XLS 1502
G.R.A.S	Pre Amplifier	26AK
ntek	Rotating microphone boom	MB01

A5. References

BS EN ISO 717-1:2013	Rating of sound insulation in buildings and of building elements. Airborne Sound Insulation.
BS EN ISO 10140-2:2010	Laboratory measurement of sound insulation for building elements – Part 2: Measurement of airborne sound insulation.



Test Report No: 24795-SRL-RP-XT-001-PI

Page 13 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

Appendix B – Test Procedure

Measurement of Sound Transmission in accordance with BS EN ISO 10140-2: 2010 - TP33

In the laboratory, airborne sound transmission is determined from the difference in sound pressure levels measured across a test sample installed between two reverberant rooms. The difference in measured sound pressure levels is corrected for the amount of absorption in the receiving room. The test is done under conditions which restrict the transmission of sound by paths other than directly through the sample. The source sound field is randomly incident on the sample.

The test sample is located and sealed in an aperture within the block and plasterboard wall between the two rectangular reverberant or acoustically "live" rooms, both of which are constructed from 215mm brick with reinforced concrete floors and roofs. The brick wall has dimensions of 3.9m wide x 2.9m high and forms the whole of the common area between the two rooms.

One of the rooms termed the source room has a nominal volume of 55 cubic metres and is isolated by the use of resilient mountings and seals, from the surrounding structure and the adjoining room. The adjoining receiving room has a nominal volume of 53 cubic metres.

Broad band noise is produced in the source room from an electronic generator, power amplifier and loudspeaker. The resulting sound pressure levels in both rooms are sampled, filtered into one third octave band widths, integrated and averaged by means of a Real Time Analyser using a microphone on an oscillating microphone boom. The value obtained at any particular frequency is known as the equivalent sound pressure level for either source or receiving rooms. The change in level across the test sample is termed the equivalent sound pressure level difference, i.e.

$D = L_1 - L_2$

where

- D is the equivalent Sound Pressure level difference in dB
- L_1 is the equivalent Sound Pressure level in the source room in dB
- L_2 is the equivalent Sound Pressure level in the receiving room in dB





Page 14 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

The Sound Reduction Index (R), also known by the American terminology Sound Transmission Loss, is defined as the number of decibels by which sound energy randomly incident on the test sample is reduced in transmitting through it and is given by the formula:

 $R = D + 10\log 10 \frac{s}{A}$ in decibels

where

- S is the area of the sample
- A is the total absorption in the receiving room

both dimensions being in consistent units

The Sound Reduction Index is an expression of the laboratory sound transmission performance of a particular element or construction. It is a function of the mass, thickness, sealing method of mounting etc., and is independent of the overall area of the sample.

However, when an example of this construction is installed on site, the sound insulation obtained will depend upon its surface area, as well as the absorption in the receiving room. The larger the area the greater the sound energy transmitted. Also, the overall sound insulation is affected by the sound transmission through other building elements, some of which may have an inferior performance to the sample tested. In practice, therefore, the potential sound reduction index of a construction is not fully realised on site. Furthermore, the sound reduction index of a particular sample of that construction can only be measured accurately in a laboratory, because only under such controlled conditions can the sound transmission path be limited to the sample under test.

 $R_{\mbox{\tiny w}},\,C$ and $C_{\mbox{\tiny tr}}$ have been calculated in accordance with the relevant section of

BS EN ISO 717-1:2013 from the results of laboratory tests carried out in accordance with

BS EN ISO 10140-2:2010.





Page 15 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

Appendix C – Measurement Uncertainty

BS EN ISO 10140-2: 2010 - TP33

The following values of uncertainty are based on a standard uncertainty multiplied by a coverage factor of k = 2, which provides a level of confidence of approximately 95%.

Frequency, Hz	Uncertainty, ± dB
100	3.2
125	2.9
160	2.5
200	2.5
250	1.8
315	1.8
400	1.5
500	1.5
630	1.2
800	1.2
1000	1.2
1250	1.2
1600	1.2
2000	1.2
2500	1.2
3150	1.2
Temperature	±0.8 °C
Humidity	±10 %RH
Static Pressure	±1 mbar



Test Report No: 24795-SRL-RP-XT-001-PI

Page 16 of 16

Date: 17/05/2021

This report shall not be reproduced, except in full, without written approval of SRL Technical Services Limited

Laboratory Holbrook House The Street Little Waldingfield Sudbury Suffolk CO10 0TF Tel: +44 (0)1787 247595

Website: www.srltsl.com e-mail: srl@srltsl.com

Registered Name and Address:

SRL Technical Services Limited Holbrook House Little Waldingfield Sudbury Suffolk CO10 0TF

Registered Number: 907694 England

